US ERA ARCHIVE DOCUMENT

U.S. ENVIRONMENTAL PROTECTION AGENCY, REGION V POLLUTION/SITUATION REPORT #192



KALAMAZOO RIVER/ENBRIDGE SPILL – REMOVAL SITE # Z5JS MARSHALL, MICHIGAN LATITUDE: 42.2395273; LONGITUDE: -84.9662018



To: Susan Hedman, U.S. EPA Regional Administrator

James Sygo, MDEQ Michelle DeLong, MDEQ Dr. Linda Dykema, MDCH

Deb Cardiff, Kalamazoo County Public Health Richard Fuller, Kalamazoo County Sheriff's Office

James Rutherford, Calhoun County Public Health Department Durk Dunham, Calhoun County Emergency Management Scott Corbin, Allegan County Emergency Management

Tiffany Eichorst, City of Battle Creek Cheryl Vosburg, City of Marshall

Christine Kosmowski, Calhoun County Water Resources Commissioner

From: Jeffrey Kimble, U.S. EPA, Federal On-Scene Coordinator

Date: 11/14/2013

Operational Period: 0700 hours 10/21/2013 through 0700 hours 10/28/2013

0700 hours 10/28/2013 through 0700 hours 11/04/2013

Reporting Period: 0700 hours 10/21/2013 through 0700 hours 11/04/2013

1. Site Data

Site Number:Z5JSResponse Type:EmergencyResponse Authority:OPAIncident Category:Removal ActionResponse Lead:RPNPL Status:Non-NPI

Response Lead: RP **NPL Status:** Non-NPL **Mobilization Date:** 7/26/2010 **Start Date:** 7/26/2010

FPN#: E10527

2. Operations Section

• The organizational response structure consisted of the following Branches: 1) Environmental Field Teams; and 2) Dredge Operations.

2.1 Environmental Field Teams Branch

2.1.1 Science Division

- E4.0 Containment System monitoring and maintenance continued in accordance with the 2012 Morrow Lake Delta and Morrow Lake Monitoring and Management Work Plan (November 15, 2012). Monthly bathymetry was conducted upstream and downstream of the containment structures from October 21 24, 2013. Monthly poling was conducted from October 28 November 1, 2013.
- Monthly Walling tube sampling was conducted from October 28 31, 2013 in accordance with the 2013 Submerged Oil Removal and Assessment Work Plan (May 13, 2013).
- Sediment trap monitoring continued in accordance with the approved Sediment Trap Monitoring and Maintenance Plan (July 10, 2012). From October 28 31, 2013, Enbridge conducted the quarterly bathymetry survey at the MP 14.75 sediment trap subsequent to completion of dredge activities.

2.1.2 Water Operations Division

- Enbridge monitored and maintained 4,900 feet of surface hard boom and 4,250 feet of subsurface half-curtain at the E 4.0 Containment System.
- Management of oil sheen and/or globules continued throughout the period. No responses were conducted during this reporting period.

2.1.3 Compliance Division

- On October 23, 2013, MDEQ issued Enbridge a dredge permit modification for the MP 10.40 sediment trap.
- On October 28, 2013, MDEQ issued Enbridge a dredging modification to the MDEQ permit for oil recovery at the MP 36.10 sediment trap.
- As of the close of the reporting period, Enbridge's dredging modification supplemental information to the MDEQ permit for oil recovery at the MP 26.00 sediment trap is in review with MDEQ.
- As of the close of the reporting period, Enbridge's MDEQ dredging permit application for the MP 28.25 sediment trap is in review with MDEQ. The permit application will require a full review by MDEQ and a public notice period.
- U.S. EPA outlined in Section 47 of the March 14, 2013 Administrative Order and subsequently verbally
 communicated to Enbridge that it is Enbridge's responsibility to apply for MDEQ dredging permits and
 to modify existing permits to include dredging as the submerged oil recovery method, in a timeframe
 which allows for compliance with the U.S. EPA Order deadline of December 31, 2013. Enbridge has
 elected to wait for triggers to occur before applying for or modifying the existing MDEQ dredging
 permits.
- Enbridge has not started dredging activities in the Delta area of Morrow Lake.

2.2 Dredge Operations Branch

2.2.1 Ceresco, Mill Ponds, Morrow Lake and Sediment Trap Divisions

- Dredging of the pilot channel was completed at the Ceresco Dam impoundment on October 19, 2013. Pilot channel sidewall containment installation was completed on October 29, 2013. Dam notching and drawdown began on October 30, 2013.
- Dredging continued at the Mill Ponds impoundment. Dredging operations included water treatment and discharge, containment installation and maintenance, dewatering of dredged sediment in Geotube bags, sediment solidification and transportation for off-site disposal.
- Sediment removal activities continued at the MP 21.50 RDB sediment trap. Activities included installation of sheet piling, dewatering, water treatment and discharge, excavation of oiled sediment, solidification and transportation for off-site disposal.
- Table 1 presents the quantities of water treated at each dredge location during the reporting period. Table 2 presents the estimated dredge waste on-site in Geotube bags, the cumulative estimated dredge waste, and the cumulative waste shipped off-site for disposal.
- Work area air monitoring, dissolved oxygen water quality monitoring, and turbidity water quality monitoring were conducted during dredging activities.

• As of the close of the reporting period, Enbridge has not provided U.S. EPA with evidence of substantive progress for oil removal in Morrow Lake or the Morrow Lake Delta.

2.2.2 Waste Management Division

- Cumulative quantities of soil, debris, and liquid shipped off-site during the response are presented in Tables 3 and 4.
- The cumulative quantity of recovered oil has been estimated using actual waste stream volumes, analytical data, and physical parameters of oil-containing media. A summary of the estimated volume of recovered oil is presented in Table 5.

3. Planning Section

3.1 Situation Unit

- On October 21, 2013, Situation Unit personnel discontinued conducting routine daily field observations.
- During the reporting period, overflights were conducted on October 23 and 29, 2013 to document all operational areas and locations of oil sheen and/or globules. Photographs were taken and distributed to project participants during the weekly Consolidated ICS Meetings.

3.2 Environmental Unit

- U.S. EPA, USGS, and the U.S. Army Corps of Engineers held weekly meetings to discuss Hydrodynamic Model (HDM) activities, including planned on-site erodability testing fieldwork by the U.S. Army Corps of Engineers which will be conducted during the next operational period.
- U.S. EPA continued review of sediment sample analytical results from legacy cores collected by Enbridge.
- U.S. EPA continued review of oil fingerprinting analytical results from sheen and globule samples collected by Enbridge to determine the presence/absence of Line 6B oil.

3.3 Documentation Unit

• The Documentation Unit continued organizing and archiving electronic and paper files for post-incident use.

3.4 Resource Unit

The Resources Unit continued to support production of the Incident Action Plan (IAP), supported the
planning efforts of operations, and provided information to Logistics personnel in order to properly
prepare and procure resources.

4. Command

4.1 Safety Officers

• Enbridge safety personnel continued conducting work-site safety inspections and implementing the plan for integration of public safety and worker safety on the Kalamazoo River.

 The USCG is providing the U.S. EPA with on-site support by monitoring safety throughout all active work areas.

4.2 Public Information

• The number of public inquires reported by Enbridge for this period is presented in Table 7.

5. Finance

• The current National Pollution Funds Center (NPFC) ceiling is \$63.25 million. Approximately 91.9% of the ceiling has been spent through November 3, 2013. The latest average 14-day burn rate was \$23,655 per day. These cost summaries reflect only U.S. EPA-funded expenditures for the incident. A summary of these expenses is presented in Table 8.

6. Scientific Support Coordination Group (SSCG)

• No activities were conducted during this operational period.

7. Participating Entities

- U.S. EPA and MDEQ continued to meet bi-weekly with a group of stakeholders to discuss how to continue to effectively communicate, share information about site progress, and receive feedback about the communication needs of the local communities.
- For a list of cooperating and assisting agencies, see SITREP #51 (Sections 3.2 and 3.3).

8. Personnel On-Site

• Staffing numbers for the entities and agencies active in the response are presented in Table 9.

9. Source of Additional Information

• For additional information, refer to http://www.epa.gov/enbridgespill. For sampling analysis data, see http://response.enbridge.com/response/.

10. Clean-up Progress Metrics

Table 1 - Water Treated During Dredging Operations for the Reporting Period

Dredge Location	Water Treated (gal)
Ceresco	1,933,920
Mill Ponds	4,000,304
Sediment Traps	14,773,296
Morrow Lake	0

Table 2 – Dredging Waste (as of 11/04/2013)

Waste Stream	Estimated Dredge Waste On-Site in Geotube bags (yd³)	Cumulative Estimated Dredge Waste (yd³)	Cumulative Waste Shipped Off-Site for Disposal (tons)			
Ceresco	23,878	97,006	73,088			
Mill Ponds	4,677	11,797	7,095			
Sediment Traps	120	8,877	8,742			
Morrow Lake	N/A	0	0			
C0.4/Wildlife Center/C3.2/FTC	N/A	809*	794			
Total	28,675	118,489	89,719			

^{*}Estimated dredge waste related to oily debris.

Table 3 - Soil and Debris Shipped Off Site (as of 11/04/2013)

Table 5 - Son and Debt is Shipped Off Site (as of 11/04/2015)										
Waste Stream	Cumulative	Disposal Facility								
$Haz Soil (yd^3)$	19,644	Envirosafe (Oregon, OH)								
Non-Haz Soil (yd ³)	151,404	SET/C&C								
Non-Haz Soil (yd ³)	902	SET/Ottawa County Farms								
Non-Haz Soil (yd ³)	9,357	SET/WM Westside								
Non-Haz Soil & Debris (yd³)	64,815	Westside Recycling (Three								
(Excluding 2010 Ceresco Dredge)	04,613	Rivers, MI)								
Non-Haz Soil (yd³)	5,562	EQ/Republic (Marshall, MI)								
(2010 Ceresco Dredge Only)	3,302	LO Republic (Marshall, MI)								
Haz Debris (yd³)	12,075	EQ/Michigan Disposal (Wayne,								
Huz Deoris (ya)	12,073	MI) and Republic (Marshall, MI)								
Non-Haz Household Debris (ton)	2,085	SET/C&C								
Non-Haz Impacted Debris (ton)	10,961	SEI/C&C								

Shaded and italicized items are discontinued waste streams.

Table 4 - Liquid Shipped Off-Site (as of 11/04/2013)

		,	Cumulative Volume
Stream	Destination Company	Destination Location	(gallons)†
Non-Haz Water	Liquid Industrial Waste	Holland, MI	1,480,407
Non-Haz Water	Plummer	Kentwood, MI	657,523
Non-Haz Water	Dynecol	Detroit, MI	981,792
Non-Haz Water	Battle Creek POTW	Battle Creek, MI	1,143,280
Hazardous Water	Dynecol	Detroit, MI	3,594,579
Oil	Enbridge Facility	Griffith, IN	766,288
Other Material	Entiting Facility	Grijjiin, nv	1,405,525
Treated Non-Haz Water	Liquid Industrial Waste	Holland, MI	370,200
Treated Non-Haz Water	Plummer	Kentwood, MI	4,976,140
Hazardous Water	Safety Kleen ^a		825
Treated Non-Haz Water	Dynecol	Detroit, MI	150,700
Treated Non-Haz Water	Battle Creek POTW	Battle Creek, MI	1,968,700
		Total	17,495,959

Shaded and italicized items are discontinued waste streams.

Table 5 – Estimated Recovered Oil (as of 11/04/2013)

Waste Stream Containing Recovered Oil	Destination Company	Destination Location	Estimated Oil Volume in Waste Stream (gallons)
Soil	C&C Landfill	Marshall, MI	17,358*
Impacted Soil & Debris	Envirosafe/ Westside RDF	Oregon, OH	278,665
Geotube Sediment - (Impacted Sediment)	Envirosafe/ Westside RDF	Oregon, OH	1,298
Debris - (Roll Off Boxes with Impacted Sorbents, boom, pads, plastic, PPE, vegetation, and biomass)	EQ Michigan	Belleville, MI	39,964*
Frac Tank City - Influent to Carbon Filtration System	C&C Landfill	Marshall, MI	8,109
	Dynecol	Detroit, MI	
Frac Tank City - Water	Liquid Industrial Waste Services, Inc.	Kentwood, MI	46,179
	Plummers Env. Inc.	Holland, MI	
	BC POTW	Battle Creek, MI	
Ceresco Pretreatment System	C&C Landfill	Marshall, MI	90
A-1 Pretreatment System	C&C Landfill	Marshall, MI	9
Oily Water - RPP	Enbridge Facility	Griffith, IN	766,288
		Total	1,157,961

Shaded and italicized items represent discontinued waste streams.

[†] Cumulative quantities may not reconcile with previous reports (due to auditing).
a New Age lab water and methanol mix generated by mobile laboratory.

^{*}Total updated for analytical received after report generation.

Table 6 - Samples Collected By Enbridge

			November/October 2013												
Sample Type	Total	2	1	31	30	29	28	27	26	25	24	23	22	21	20
Surface Water	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Private Well	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Groundwater	98	0	7	11	14	7	12	0	0	10	12	4	9	12	0
Sediment	36	0	0	33	0	0	0	0	0	3	0	0	0	0	0
Soil	2	0	0	0	0	0	0	0	0	0	0	2	0	0	0
Product	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Dewatering	28	0	0	0	2	6	4	0	0	0	0	4	6	6	0
Sheen	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Table 7 – Public Inquiries Received by Enbridge

	November/October 2013													
Location/Med	1	31	30	29	28	27	26	25	24	23	22	21	20	19
Marshall Community Center	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Oil Spill Public Information Hotline	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Website	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Public Inquiries	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Table 8 - Financial Summary (as of 11/03/2013)

Table 6 - Financial Summary (as 01 11/0		dod (Cumulativa)
Item	Expend	ded (Cumulative)
ERRS Contractors	_	
EQM (EPS50802) T057	\$	1,199,522
T060	\$ \$	213,636
LATA (EPS50804) T019	\$	1,161,082
ER LLC (EPS50905) T040	\$	<u>683,330</u>
Total ERRS Contractors	\$	3,257,571
Other Contractors		
Lockheed Martin (EPW09031) – TAGA Support	\$	198,379
Lockheed Martin (EPW09031) -Biodegradability Study		61,886
T&T Bisso (EPA:HS800008)	\$	882,087
Total Other Contractors	\$	1,142,352
START Contractor – WESTON (EPS50604)		
T030-Response	\$	35,700,611
Community Relations	\$	114,563
T032-Sampling	\$	161,045
T037-Doc Support		2,058,443
Total START Contractor	\$	38,034,662
Response Contractor Sub-Totals	\$	42,441,257
U.S. EPA Funded Costs: Total U.S. EPA Costs	\$	6,704,295
Pollution Removal Funding Agreements		
Total Other Agencies	\$	3,437,081
Indirect Cost (16.00%)	\$	3,520,519
Indirect Cost (8.36%)-payments after 10/1/2011	\$	1,310,859
Indirect Cost (10.15%)-payments after 10/1/2012	\$	1,118,566
Cost Documentation/Billing Admin Fee (2.93%)*	\$	556,697
	· · · · · · · · · · · · · · · · · · ·	,
Total Est. Oil Spill Cost	\$	58,138,784
Oil Spill Ceiling Authorized by USCG	\$	63,250,000
Oil Spill Ceiling Available Balance**	\$	5,111,216
Shaded and italicized items are discontinued		

Shaded and *italicized* items are discontinued

^{*} Effective on EPA Enbridge costs billed to USCG for bills issued after 6/5/12.

^{**}USCG personnel may increase to compensate for EPA not having all available funds to fully staff the site to execute the OPA Project Plan as approved through 12/31/2013. USCG personnel will fill gaps in contractor/EPA staff planned resources as appropriate.

Table 9 - Personnel On-Site

	October 2013													
Agency/Entity	3	2	1	31	30	29	28	27	26	25	24	23	22	21
U.S. EPA	0	0	2	2	3	3	2	0	0	2	2	4	2	2
START	1	4	15	15	16	14	14	1	4	11	13	14	14	14
MDEQ	0	0	4	5	4	7	4	0	0	2	3	9	4	4
MDEQ Contractors	0	0	0	2	3	3	2	0	0	0	2	2	2	2
Other Agencies	3	3	3	1	4	1	3	3	3	2	1	4	3	3
Enbridge – Environmental Field Teams – Science*	4	16	32	35	37	36	36	2	11	30	34	35	37	31
Enbridge – Environmental Field Teams – Water Ops*	11	35	38	40	46	48	46	18	51	67	62	68	67	70
Enbridge – Dredge Operations – Ceresco*	6	79	84	89	87	90	88	0	90	96	106	110	123	124
Enbridge – Dredge Operations – Mill Ponds*	0	52	52	52	56	53	52	1	46	51	55	52	48	47
Enbridge – Dredge Operations – Delta/Morrow Lake*	0	6	9	4	6	0	1	0	0	2	1	0	0	0
Enbridge – Dredge Operations – Sediment Traps*	0	4	25	32	30	32	28	14	26	31	32	29	30	31
Enbridge – Waste Management*	0	72	83	76	83	92	92	0	84	85	73	73	70	70
Enbridge – Office Support*	3	21	39	45	44	46	48	7	22	49	48	48	49	45
Total	28	292	386	398	419	425	416	46	337	428	432	448	449	443

^{*}Enbridge Operations and Field include Enbridge and contractors as reported by Enbridge